

CERTIFICATE

No.: 20950001

Welding of railway vehicles and components according to EN 15085-2

This is to certify that

EPSILON NDT ENDÜSTRİYEL KONTROL SİSTEMLERİ SAN. VE TİC. A.Ş.

Headquarters : 19 Mayıs Mah. Dr. Şevket Bey Sk. Polat Çiftçiler Apt. No:3 /A-B
PK:34360 Şişli İstanbul/ Turkey

Factory : Eskişehir OSB 21.Cad. No:39 Eskişehir /Turkey

is qualified to perform welding work within the range of certification of:
Certification level CL1 according to EN 15085-2

Field of Applications:

Product Design and Production, Metal Structure, Welded Railway Vehicles and Components

Range of Qualification:

Material Groups TSE CEN ISO/TR EN 15608	Methods of Welding TS EN ISO 4063	Dimensions	Remarks
1.2	135	BW:3 to 12, FW:3 to 12	BW,FW
1.2	135	BW:10 to 40, FW:3 to 40	BW,FW
1.2	135	FW: 3 to 40	FW
1.2	135	FW: 3 to 12	FW
1.2	121	FW: 3 to 40	FW

The certificate is valid for circumstances that defined above, as long as the rules of the standard and certificate program are followed.

Welding Coordinator Personnel Burak TEKİN , IWE born : 30.03.1983
Deputy with Equal Rights -
Deputy Niyazi KAVLAK, Level C born : 20.12.1992
Auditor Sedat SAĞLAM



Validity Period: 14.09.2020 to 13.09.2023

Istanbul
Location

14/09/2020
Issue Date



**PRODUCT
INSPECCO
CERTIFICATION**
Yavuz KEÇECİ
General Manager

INSPECCO Belgelendirme ve Gözetim Hizmetleri A.Ş.

ŞERİFALİ MAH. AÇIKYÜZ SOKAK. NO: 2-3
INSPECCO PLAZA, ÜMRANIYE
İSTANBUL - TÜRKİYE
+90 216 313 14 20

Certificate no.: 20950001

General Regulations

according to EN 15085-2

Revocation of the Certificate

The national safety authority or the manufacturer certification body issuing this certificate may revoke the certificate if:

- there are justified doubts as to the proper execution of the welding work according to the stated standards,
- there are justified doubts as to the proper welding coordination according to the stated standards,
- no recognized welding coordinator is available any longer,
- no valid qualification test certificates for the welders and welding operators according to the specified standards are available,
- welders or welding operators without tested qualifications have been entrusted with the execution of welding work under the stated standards,
- other conditions according to the stated standards are no longer satisfied,
- the manufacturer certification body was refused an opportunity to perform the annual verification,
- the welding manufacturer waives the certificate

The welding manufacturer shall acknowledge the revocation in writing to the manufacturer certification body. The manufacturer certification body shall notify the national safety authority.

If a valid certificate is to be renewed, the renewal must be applied for with the manufacturer certification body at least **two months** before the end of the period of validity of the current certificate.

Distribution List:

1. Applicant (original)
2. Files



INSPECCO Belgelendirme ve Gözetim Hizmetleri A.Ş.

ŞERİFALİ MAH. AÇIKYÜZ SOKAK. NO: 2-3

INSPECCO PLAZA, ÜMRANİYE

İSTANBUL - TÜRKİYE

+90 216 313 14 20